

Norman H. Bangerter, C. Dee C. Hansen, Executive L. Dianne R. Nielson, Ph.D., Division Dt.

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

October 20, 1986

CERTIFIED RETURN RECEIPT REQUESTED (P 402 458 643)

Mr. William D. Moeller American Consolidated Mining Company 405\$South 100 East Pleasant Grove, Utah 80462

Dear Mr. Moeller:

Re: Permitting Requirements, American Consolidated Mining Operations near Gold Hill and Clifton, Utah, ACT/045/019 and DOE/045/026, Tooele County, Utah

This letter is to request that American Consolidated Mining Company fulfill the permitting requirements for its operations in Tooele County, Utah. A field inspection of the operations was conducted recently, as well as a file review, and disclosed the following actions are necessary:

Yellow Hoummer Site

Surface disturbance at this site is estimated to be approximately 10 acres. An MR-l application must be completed and forwarded to the Division for this site.

Clifton Heap Leach Site

Field inspections have identified toxic chemical problems on-site. The area appears to have been inactive for some time. An MR-4 form must be completed for this site.

Unnamed Site, SW 1/4, Section 1, Township 8 South, Range 18 West

This site appears to be under 2 acres in disturbance. An MR-4 form must be filed for this site.

Page 2 Mr. W. D. Moeller ACT/045/019 & DOE/045/026 October 20, 1986

Additionally, the Division requests a report on the status and location of all American Consolidated operations in Utah to clarify site locations. Previous information filed with this office is not clear as to the number and locations of operations.

Enclosed are MR-1 and MR-4 forms for you to complete and return to the Division. Please submit the completed forms and a Status and Location Report to the Division by November 21, 1986.

Sincerely,

Lowell P. Braxton

Administrator

Mineral Resource Development and Reclamation Program

JJW/djh cc: J. Whitehead R. Smith 0800R/51